

Ted Strickland, Governor Lee Fisher, Lt. Governor Chris Korleski. Director

November 11, 2010

American Energy Corp - Century Mine 43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716

Dear Permittee:

A Preliminary Compliance Review was conducted on your Discharge Monitoring Report (DMR) submitted on November 10, 2010. As detailed at the end of this letter, screening of your submitted DMR has identified possible compliance issues. Please review the information and take the appropriate action:

- If you believe the identified compliance issues are in error based on your understanding of your NPDES permit
 conditions, contact your Ohio EPA District Representative, Abbot Stevenson, at 1-800-686-7330 or
 Abbot.Stevenson@epa.state.oh.us
- Part III-12 of your NPDES permit requires that you submit an email or a letter of explanation outlining the actions you have taken or are taking to correct certain instances of non-compliance. If you have not already done so, please submit the email or letter to your Ohio EPA District representative at the following address:

Abbot Stevenson
Ohio EPA - Southeast District Office
2195 Front Street
Logan, Ohio 4313
1-800-686-7330 or Abbot.Stevenson@epa.state.oh.us

• The following web address contains useful eDMR submission information including definitions of limit violations, non-numeric violations, frequency violations, calculation of average concentrations, and correct A-code use: http://www.epa.ohio.gov/dsw/edmr/eDMR.aspx

Sincerely,

Ed Swindall ed.swindall@epa.state.oh.us Supervisor, Permits Compliance Unit Ohio EPA, Division of Surface Water



Tod Strickland, **Governor** Lee Fisher, Lt. **Governor** Chris Korleski, **Director**

Preliminary Compliance Report

Facility:

American Energy Corp - Century Mine

Permit No.:

0IL00091*GD

Report Period:

October 2010

Date Received:

11/10/2010

			Reporting			Permit	Reported
Station	Type	Date	Code	Parameter	Limit Type	Limit	Value
015	Limit	10/3/2010	00400	pH	Daily Conc.	9.0	9.11



Use this form to report non-compliance that is the result of any violation of a daily maximum discharge limit for any of the pollutants listed by the Director in your NPDES permit (see Part III, Section 12 of your NPDES permit for details). The form should be completed and e-mailed to the appropriate Ohio EPA inspector, or Ohio EPA office using one of the following addresses:

Southeast District Office: Southwest District Office: Northwest District Office: Northeast District Office: sedo24hournpdes@epa.state.oh.us swdo24hournpdes@epa.state.oh.us nwdo24hournpdes@epa.state.oh.us nedo24hournpdes@epa.state.oh.us cdo24hournpdes@epa.state.oh.us co24hournpdes@epa.state.oh.us

Central District Office: Central Office:

Permittee Information	
Name of permittee:	American Energy Corporation
NPDES Permit number:	OIL00091*GD
Contact name for permittee:	Cody Mozena
Contact telephone number:	740-310-9428
Exceeded limit	
Parameter name:	На
Provide type of limit exceeded, e.g.	Daily Concentration
concentration, loading, etc.	
Extent of exceedance	
Provide permit limit, e.g. 10 ug/l	6.00 - 9.00 S.U.
Measured exceedance (include units):	9.11 S.U.
Cause of exceedance	
Provide an explanation for the cause of the permit limit exceedance:	Water Quality Management personnel currently operate a small gasoline circulation pump at P015 to ensure proper dispersion of treatment chemical and promote inlet flow aeration. These processes raise pH and assist in settling parameters out of solution. This pump was mistakenly allowed to run throughout the night of 10/2/2010, causing a quick increase in the pH level. The pump was shut down by early morning on 10/3/2010. The field pH from 10/4/2010 shows the pH is within permitted discharge limits for pH.
Period of exceedance	
Exact time period of exceedance	10/3/2010 7:30 A.M.
(include times and dates):	
If uncorrected, expected duration	
If the exceedance is not yet corrected, provide the expected time period during which it is anticipated to continue:	The exceedance has been corrected.
Steps to address exceedance	
Describe all the steps taken to reduce, eliminate, or prevent future occurrence of the exceedance(s):	 The circulation pump at P015 is now only being operated during times of increased inlet flow. The pump is only allowed enough fuel to permit circulation for a few hours removing operator error.
	 Daily calls to management are now made by field personnel to ensure the pump is only running when necessary.

Ohio EPA Form 4499 Printed on Recycled Paper





Ted Strickland, Governor Lee Fisher, Lt. Governor Chris Korleski, Director

June 16, 2010

American Energy Corp - Century Mine 43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716

Dear Permittee:

A Preliminary Compliance Review was conducted on your Discharge Monitoring Report (DMR) submitted on June 14, 2010. As detailed at the end of this letter, screening of your submitted DMR has identified possible compliance issues. Please review the information and take the appropriate action:

- If you believe the identified compliance issues are in error based on your understanding of your NPDES permit
 conditions, contact your Ohio EPA District Representative, Abbot Stevenson, at 1-800-686-7330 or
 Abbot.Stevenson@epa.state.oh.us
- Part III-12 of your NPDES permit requires that you submit an email or a letter of explanation outlining the actions you
 have taken or are taking to correct certain instances of non-compliance. If you have not already done so, please submit
 the email or letter to your Ohio EPA District representative at the following address:

Abbot Stevenson
Ohio EPA - Southeast District Office
2195 Front Street
Logan, Ohio 4313
1-800-686-7330 or Abbot Stevenson@epa.state.oh.us

• The following web address contains useful eDMR submission information including definitions of limit violations, non-numeric violations, frequency violations, calculation of average concentrations, and correct A-code use: http://www.epa.ohio.gov/dsw/edmr/eDMR.aspx

Sincerely,

Ed Swindall ed.swindall@epa.state.oh.us Supervisor, Permits Compliance Unit Ohio EPA, Division of Surface Water





Environmental Protection Agency

Ted Strickland, Governor Lee Pisher, Lt. Governor Chris Korleski, Director

Preliminary Compliance Report

Facility:

American Energy Corp - Century Mine

Permit No.:

0IL00091*GD

Report Period:

May 2010

Date Received:

6/14/2010

Station	Type	Date	Reporting Code	Parameter .	Limit Type	Permit Limit	Reported : Value
017	Limit	5/1/2010	00610_	Nitrogen, Ammonia (NH3)	Monthly Conc.	1.0	2.
017	Limit	5/19/2010	00610	Nitrogen, Ammonia (NH3)	Daily Conc.	1.5	2.6



Use this form to report non-compliance that is the result of any violation of a daily maximum discharge limit for any of the pollutants listed by the Director in your NPDES permit (see Part III, Section 12 of your NPDES permit for details). The form should be completed and e-mailed to the appropriate Ohio EPA inspector, or Ohio EPA office using one of the following addresses:

Southeast District Office: sedce
Southwest District Office: swdce
Northwest District Office: nwdce
Northeast District Office: nedce
Central District Office: cdo2
Central Office: co24

sedo24hournpdes@epa.state.oh.us swdo24hournpdes@epa.state.oh.us nwdo24hournpdes@epa.state.oh.us nedo24hournpdes@epa.state.oh.us cdo24hournpdes@epa.state.oh.us co24hournpdes@epa.state.oh.us

Permittee Information	
Name of permittee:	American Energy Corporation
NPDES Permit number:	OIL00091*GD
Contact name for permittee:	Cody Mozena
Contact telephone number:	740-310-9428
Exceeded limit	
Parameter name:	Nitrogen, Ammonia (NH3)
Provide type of limit exceeded, e.g.	Daily Concentration & Monthly Concentration
concentration, loading, etc.	
Extent of exceedance	
Provide permit limit, e.g. 10 ug/l	Daily Conc. Of 1.5 mg/l & Monthly Conc. Of 1.0 mg/l
Measured exceedance (include units):	Daily Measurement of 2.6 mg/l & Monthly Measurement of 2 mg/l
ause of exceedance	
Provide an explanation for the cause of the permit limit exceedance:	Mechanical failure within the treatment facility has led to the plant not functioning at full operating capacity. We found the new #2 dosing pump which was installed in March lost a bearing causing the pump to fail. The failure of the #2 pump within the dosing tank has reduced the ability of the tank to function properly. The function of this pump is essential to maintaining proper flow throughout the treatment system. If a failure, or in our case reduction of pumping force occurs, proper flow and tank holding times cannot be achieved within the system, creating possible backups affecting the ability of each tank to properly function and settle out the necessary wastewater constituents.
Period of exceedance	5400040 0 F0 D M
Exact time period of exceedance	5/19/2010 2:50 P.M.
(include times and dates):	
If uncorrected, expected duration	5/30/2010
If the exceedance is not yet corrected, provide the expected time period during which it is anticipated to	3/30/2010
continue:	
Steps to address exceedance	
Describe all the steps taken to reduce,	Corrective actions taken to ensure NH3 levels will be discharged within permit
eliminate, or prevent future occurrence	guidelines include: American Energy is in the process of obtaining and installing
of the exceedance(s):	the necessary parts to repair items within the #2 pump. This will ensure correct
• • • • • • • • • • • • • • • • • • • •	water treatment and allow water to properly pass through the treatment plant.
	Fixing the pump will also allow monitoring personnel to set timing where each
	pump will run for twelve hours at a time. This will alleviate system stress from
	only having one pump continuously running and should prevent future failures.

Ohio EPA Form 4499 Printed on Recycled Paper





The testing lab has been requested to now email results to the water quality management group immediately upon completion of testing. In the interim, until the required parts needed to correct failure are obtained and installed, American Energy will remove waste from the system as needed to help maintain discharge compliance of the facility.



Environmental Protection Agency

Tod Strickland, Governor Lee Fisher, Lt. Governor Chris Korleski, Director

July 15, 2010

American Energy Corp - Century Mine 43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716

Dear Permittee:

A Preliminary Compliance Review was conducted on your Discharge Monitoring Report (DMR) submitted on July 14, 2010. As detailed at the end of this letter, screening of your submitted DMR has identified possible compliance issues. Please review the information and take the appropriate action:

- If you believe the identified compliance issues are in error based on your understanding of your NPDES permit conditions, contact your Ohio EPA District Representative, Abbot Stevenson, at 1-800-686-7330 or Abbot.Stevenson@epa.state.oh.us
- Part III-12 of your NPDES permit requires that you submit an email or a letter of explanation outlining the actions you
 have taken or are taking to correct certain instances of non-compliance. If you have not already done so, please submit
 the email or letter to your Ohio EPA District representative at the following address:

Abbot Stevenson
Ohio EPA - Southeast District Office
2195 Front Street
Logan, Ohio 4313
1-800-686-7330 or Abbot.Stevenson@epa.state.oh.us

• The following web address contains useful eDMR submission information including definitions of limit violations, non-numeric violations, frequency violations, calculation of average concentrations, and correct A-code use: http://www.epa.ohio.gov/dsw/edmr/eDMR.aspx

Sincerely,

Ed Swindall ed.swindall@epa.state.oh.us Supervisor, Permits Compliance Unit Ohio EPA, Division of Surface Water



Ted Strickland, Governor Lee Fisher, Lt. Governor Chris Korleski, Director

Preliminary Compliance Report

Facility: American Energy Corp - Century Mine

Permit No.: 0IL00091*GD

Report Period: June 2010

						Permiti	Reported :
Station	Тур⊕	Date	Code	Parameter 430	Limit: Type	Limiti	- Value
017	Limit	6/1/2010	00610	Nitrogen, Ammonia (NH3)	Monthly Conc.	1.0	4.9045
017	Limit	6/2/2010	00610	Nitrogen, Ammonia (NH3)	Daily Conc.	1.5	9.
017	Limit	6/1/2010	31616	Fecal Coliform	Monthly Conc.	1000	6600.
017	Limit	6/28/2010	31616	Fecal Coliform	Daily Conc.	2000	6600.

Date Received:

7/14/2010



Use this form to report non-compliance that is the result of any violation of a daily maximum discharge limit for any of the pollutants listed by the Director in your NPDES permit (see Part III, Section 12 of your NPDES permit for details). The form should be completed and e-mailed to the appropriate Ohio EPA inspector, or Ohio EPA office using one of the following addresses:

Southeast District Office: Southwest District Office: Northwest District Office: Northeast District Office: Central District Office:

Central Office:

sedo24hournpdes@epa.state.oh.us swdo24hournpdes@epa.state.oh.us nwdo24hournpdes@epa.state.oh.us nedo24hournpdes@epa.state.oh.us cdo24hournpdes@epa.state.oh.us co24hournpdes@epa.state.oh.us

Permittee Information			
Name of permittee:	American Energy Corporation		
NPDES Permit number:	OIL00091*GD		
Contact name for permittee:	Cody Mozena		
Contact telephone number:	740-310-9428		
Exceeded limit			
Parameter name:	Nitrogen, Ammonia (NH3) Fecal Coliform		
Provide type of limit exceeded, e.g. concentration, loading, etc.	Daily Concentration & Monthly Concentration		
Extent of exceedance			
Provide permit limit, e.g. 10 ug/l	Daily Conc. of 1.5 mg/l & Monthly Conc. of 1.0 mg/l (NH3) Daily Conc. of 2000 CFU/100ml & Monthly Conc. of 1000 CFU/100ml (Fecal Coliform)		
Measured exceedance (include units):	Daily Measurement of 9 mg/l & Monthly Measurement of 4.9 mg/l (NH3) Daily & Monthly Measurement of 6600 (Fecal Coliform)		
Cause of exceedance			
Provide an explanation for the cause of the permit limit exceedance:	Mechanical failure within the treatment facility has led to the plant not functioning at full operating capacity. One of the two aeration blowers failed early in the month of May, reducing our ability to lower levels of Ammonia. The oxygen introduced by the aeration blowers allows monitoring personnel to control the level of Ammonia within the system. As described by the plant operator, aeration provided by each blower helps to reduce NH3 levels. This step occurs before entering the clarification tank. The combination of these steps allows for proper treatment and settling time. The flow equalization pump ensures proper settling time of parameters within the treatment system. The E.Q. tank is crucial to the system and has not been functioning properly. Both mechanical failures as well as the failure of the #2 dosing pump which was noted for May occurred in rapid succession hindering the ability of the plant operator to effectively treat the wastewater.		
Period of exceedance			
Exact time period of exceedance (include times and dates):	6/2/2010 2:40 P.M. (NH3) 6/28/2010 2:50 P.M. (Fecal Coliform)		
If uncorrected, expected duration			
If the exceedance is not yet corrected, provide the expected time period during which it is anticipated to continue:	Both exceedances have been corrected.		
Steps to address exceedance			
Describe all the steps taken to reduce, eliminate, or prevent future occurrence of the exceedance(s):	Corrective actions taken to ensure Fecal Coliform & NH3 levels will be discharged within permit guidelines include: American Energy has		

Ohio EPA Form 4499 Printed on Recycled Paper



Division of Surface Water Non-compliance Notification for Exceedance of a Daily Maximum Discharge Limit

successfully installed the necessary parts to repair all mechanical failures within the sewage treatment facility. The final mechanical issue was fixed June 28th. Wastewater will now properly pass through the treatment facility allowing the plant to correctly treat and settle out contaminates. WQM staff has asked the plant operator to compile a list of vital parts and equipment so an inventory of essential items can be developed. The testing lab is continuing to send results immediately via email to the water quality management group to shorten response time. NH3 results following the June 2 nd exceedance are within effluent limitations and Fecal Coliform results for July are below detectable limits.